



HAZEFINE <GX-2800> HAZEFINE's abundant cut pile texture can create a chic and luxurious atmosphere.

category: carpet tile

| | Composition - | surface | BCF | Nylon 100% | dyeing method | of yarn Solution I | Solution Dyed | |
|--|---------------|-------------|------------------|---------------|----------------|------------------------|---------------------|--|
| | | base fabric | Nonwo | ven Polyester | backing | PVC and Glas | PVC and Glass Fiber | |
| | | size | 500mm×500mm | | overall thicks | ness 8.5mr | n | |
| | Specification | pile height | 5.5mm (cut pile) | | | | | |
| | | gauge | 1/10 | stitch | 12.0 | yarn weight (oz/sq.yd) | 29.5 | |

| Packing | $16pcs/box = 4m^2/box$ | | | | | |
|-----------------------|---|-------------------------------------|-------------------------------------|-------------------------------|--|--|
| Net Weight | | | | | | |
| Not Weight | Critical Radiant Flux (ASTM E648) Class 1 Average CRF 0.45/cm ² or higher | | | | | |
| | Smoke Density | | | Ci | | |
| | Flame-retardant | | | | | |
| Performance | | | | | | |
| | Antistatic Less than 1.0kv (JIS L 1021-16, at 23 degrees centigrade, 25%RH) | | | | | |
| | Stain-resistant Stain Release | | | | | |
| | Formaldehyde Radiation | F [™] ☆☆☆☆ Interior-fabric | s Performance Evaluation Conference | Certified No. J08-30505 | | |
| Way of Installation | ↑ ↑ ↑ Monolithic or ↓ ↑ Quarter Turn | | | | | |
| Recommended | TOLI ECO GA Cement | (required quantity) - | for steel or plastic sub-floor | 40 to 60 gram/m ² | | |
| Adhesive from TOLI | TOLI ECO GA Cement | (required quantity) - | for mortar and wood sub-floor | 60 to 100 gram/m ² | | |
| Notes on Installation | ◆Apply the adhesive on the whole surface of the sub-floor thinly and evenly. After drying, when the adhesive becomes translucent, install the tiles. Be careful not to put the tiles too tightly. ◆Occasionally the direction of cut-piles are partly broken in part, which looks like color shading. This is one of the characteristics of cut-pile carpets and not a manufacturing defect. ◆The stripes differ in position on a tile-by-tile basis so that they will not be exactly connected between the tiles (please refer to the installation image). | | | | | |
| Others | Others Please note that the product has the indigenous odor from its materials. | | | | | |

MADE IN JAPAN









GX2801



GX2805

